

7. Photographs



7.1. Front elevation showing Ash tree



7.2. Partial front elevation and driveway



7.3. Gas pipe location to front right corner of property



7.4. Crack to porch corner – thermal shrinkage



7.5. Tree and drive



7.6. Damage to drive and highway pavement through tree root action



7.7. Damage to drive and highway pavement through tree root action



7.8. Crack and “broken back” to right boundary wall



7.9. Crack and "broken back" to right boundary wall