




**EXW01**  
Existing 4mm glass to be replaced with 6mm glass. Window to be re-beaded and decorated




**EXW02**  
Existing 4mm glass to be replaced with 6mm glass. Window to be re-beaded and decorated




**EXW03**  
Original window to be repaired and Redecorated




**EXW04**  
Modern window to be replaced




**EXW05**  
Modern window to be replaced



**EXW06**  
Modern window to be replaced



**EXW07**  
Modern window to be removed and opening increased in size for bi-folding doorset




**EXW08**  
Modern window to be replaced


**IMPORTANT NOTE - WHERE 'REPAIR' IS STATED THIS RELATES TO ORIGINAL WINDOWS OF SIGNIFICANCE WITHIN THE CONTEXT OF THE LISTED BUILDING THAT ARE IN POOR CONDITION. REPAIRS WILL GENERALLY INVOLVE THE SYMPATHETIC REPLACEMENT OF ANY DILAPIDATED SECTIONS OF FRAME, CILLS AND BEADING, REMOVAL OF EXISTING PAINT AND EASING SO THAT THE WINDOWS BECOME OPERABLE, REPLACEMENT OF ANY BROKEN OR MISSING GLASS ON A LIKE FOR LIKE BASIS, SEALING AND REDECORATING.**

- NOTES:**
- DO NOT SCALE FROM THIS DRAWING.
  - This drawing is copyright of WardmanBrown. WardmanBrown is a trading name of Wardmans Architectural Services Limited.
  - All dimensions to be verified on site prior to any shop or site works being commenced.
  - Any discrepancies to be reported to the Designer BEFORE any work is put in hand.
  - This drawing must be read in conjunction with relevant consultants and specialists drawings.
  - This drawing must be read in conjunction with the drawings specified.


- CDM 2015 - ( Refer to Project Health & Safety Information )
- HAZARDS**
- Live services adjacent/on site.
  - Excavations - Ground Collapse
  - Handling major components
  - Working at height - Falling
  - Machinery & Equipment
  - Ensure all blockwork has a minimum crushing strength of 3.5N/mm<sup>2</sup>
  - The weight of each block must not exceed 20kg




**EXW09**  
Original window to be repaired and redecorated




**EXW10**  
Original high level internal window to be redecorated




**EXW11**  
Modern window to be retained and redecorated




**EXW12**  
boarded up opening to be removed to facilitate roller shutter




**EXW13**  
boarded up opening to be increased in depth to facilitate new door




**EXW14**  
opening to be insulated internally and re-boarded




**EXW15**  
Modern window to be retained and redecorated



**EXW16**



**EXW17**




**EXW18**


Original windows to be repaired and glazing replaced with 16mm Heritage Double Glazed units

| REV | DATE   | DETAILS                 |
|-----|--------|-------------------------|
| B   | Sep 20 | Updated generally       |
| A   | Aug 20 | Window Schedule Updated |


REVISIONS:




**EXW19**  
Original windows to be repaired and glazing replaced with 16mm Heritage Double Glazed units




**EXW20**




**EXW21**  
Original window to be repaired and glazing replaced with 16mm Heritage Double Glazed units



**EXW22**  
Original window to be repaired




**EXW23**  
Original window to be repaired




**EXW24**


Existing opening to receive insulated timber framework with cedar cladding and window



**EXW25**  
Existing boarded opening to receive new timber window




**EXW26**  
Existing boarded opening to receive insulated timber framework with cedar cladding




**EXW27**  
Existing boarded opening to receive new timber window

113 Stanhope Road South  
Darlington, DL3 7SF  
Tel: 01325 460227

info@wardmanbrown.com  
www.wardmanbrown.com




**EXW28**  
Existing boarded opening to receive insulated timber framework with cedar cladding




**EXW29**


Modern windows to be replaced with new double glazed timber windows



**EXW30**




**EXW31**




**EXW32**

Original windows to be repaired and glazing replaced with 16mm Heritage Double Glazed units




**EXW33**

Existing boarded opening to receive insulated timber framework with cedar cladding




**EXW34**




**EXW35**

Existing boarded openings to be increased to accommodate balcony doorset



**EXW36**



**EXW37**

Existing bricked up frame discovered during opening up works to be replaced with new windows

**CLIENT:**  
Mr and Mrs Fox

**PROJECT:**  
123 High Street Yarn

**DRAWING TITLE:**  
Existing Window Alterations

**PURPOSE OF ISSUE:**  
**PLANNING**

**SCALE:** 1:100 @ A3

**DATE:** May 2019 | **DRAWN:LG** | **DRG REVISION:**

**DRAWING NO:** L018123-009 | **B**