

Building	Address	Permission Needed from Third Party	Flagpole location option		Comments
			Freestanding	Building Mounted	
Stockton Central Library/Contact Centre	Church Road Stockton-on-Tees TS18 1TU	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Looks to be sufficient space in the grassed area to position a flagpole Alternative option could be a wall mounted (brick section) or roof mounted
Thornaby Central Library/Contact Centre	Wrightson House, Pavilion Shopping Centre, Thornaby, TS17 7EW	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	SBC lease the use of Wrightson House for the contact centre, Thornaby Central Library and TAL facility. Permission (amendment to lease) would be required to erect a building mounted flagpole There is no identification on outside of building that SBC library is located within - may cause confusion as to whom is flying the flag ?
Thornaby Library	Riverbanks Childrens Centre Gilmour Street, Thornaby, TS17 6PF	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Dual use within building. Location nearest SBC use would need to be considered to avoid confusion
Fairfield Library	Fairfield Road Stockton-on-Tees TS19 7AJ	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Dual use within building. Location nearest SBC use would need to be considered to avoid confusion Paved area to front is in SBC option for a freestanding option
Roseworth Library	Redhill Family Hub Redhill Road Stockton-on-Tees TS19 9BX	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Building mounted option may be obscured by trees
Norton Library	87 High Street Norton Stockton-on-Tees TS20 1AE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	SBC lease ground floor of building for library provision. Permission (amendment to lease) would be required to erect a building mounted flagpole Upper floor understood to be residential accommodation - owners/tenants of these flats may object to flag being flown outside their window
Yarm Library	49 High Street, Yarm, Stockton-on-Tees, TS15 9BH	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Building already has wall bracket for mounted a Christmas Tree. Sufficient space for additional mounting for flagpole.
Ingleby Barwick Library	Ingleby Barwick Leisure Centre Blair Avenue Ingleby Barwick Stockton-on-Tees TS17 5BL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	The library is located within Ingleby Barwick Leisure - permission would be required to be agreed with Tees Active Limited who manage this building. Cladding walls would be unsuitable for wall mounted option - brick faced wall may be less visible. Roof mounted option would need investigation. There is no identification on the outside of the building that the SBC library is located within - confusion may arise if flag were to be flown as to why other TAL buildings are not flying a flag ?
Existing Flagpoles					
Stockton Town Hall Dunedin	High Street, Stockton-on-Tees, TS18 1AU Columbia Drive, Thornaby, TS17 6QZ				Flagpole already insitu Flagpole to be installed 2025
Billingham Library/Contact Centre	Queensway Billingham TS23 2LN				Funded by Community Participation Budget in 2017/18 for the erection of the British Legion flag for remembrance Sunday. Bham Town Council currently flying their flag. Room for additional flagpole in SBC owned grassed area to front of library. Site investigations would be required for all buildings to assess the structural integrity of the building if wall or roof mounted options to be looked at and also the checking of underground utility apparatus for any freestanding options
All					How the flags are to be raised/lowered would need to be considered along with any maintenance of the flagpoles - wall mounted options may require ladder or cherry picker access Revenue cost for raising/lowering and maintenance would need to be considered